

t 0800 0188 423  
 e wecare@airoptions.co.uk  
 f 0800 0188 426  
 w www.airoptions.co.uk

**Head Office**  
 Environment House  
 6 Swanbridge Industrial Park  
 Black Croft Road, Witham, Essex, CM8 3YN



## Visit Report Summary



<b>Visit Code:</b> V21071	<b>Type:</b> One Off Maintenance	<b>Start Date:</b> 30 September 2016
<b>Contract Code:</b>	<b>Customer order ref:</b>	<b>End Date:</b> 30 September 2016
<b>Site:</b> EUDELO (European Dermatology London)  <b>Address:</b> 63 BONDWAY LONDON SW8 1SJ  <b>Phone:</b> 020 7118 9500 <b>Contact:</b> (N/A)	<b>Customer:</b> EUDELO (European Dermatology London)  <b>Address:</b> 63 BONDWAY LONDON SW8 1SJ  <b>Phone:</b> 020 7118 9500 <b>Contact:</b> (N/A)	<b>Assigned Personnel:</b> Duane Murton  <b>Special Instructions for Site:</b>

**Visit Notes/Problems:**

On site for 8.30am  
 One off maintenance to six Daikin internal units and one external unit.  
 Assumed numbers, any additional units at additional cost.  
 POC £238.75 + VAT + any additional unit costs.

**Engineer Remarks:**

maintenance checks carried out to all internal unit tested in cooling and heating modes air off temperatures taken all working fine when left site.  
 unable to access condenser unit so will have to price for a return visit when access can be arranged.

Job Completion Questions		Parts Used	
Description	Answer	QTY	Description
Parts Used	none		No parts for this section
Parking Fees	14.00		
Payment Type / Value	none		
WTN No.	none		
<b>Signed On Behalf Of Air Options Ltd</b>		<b>Signed on Behalf of Customer</b>	
<b>Our Name:</b> Duane Murton	<b>Date:</b> 30 Sep 2016	<b>Your Name:</b> Jason Williams	<b>Date:</b> 30 Sep 2016
			

# Visit Report Equipment Page

**Visit Code:** V21071

**Equipment:** DAIKIN FXSQ63P7VEB - DUCTED

**Serial No:** room 8

**Location:** 5433533

**Problems / Common Fault:** (N/A)

**Remarks:**

New equipment added on handheld device

**Equipment:** DAIKIN FXAQ50PAV1 - CASSETTE

**Serial No:** E009703

**Location:** reception

**Problems / Common Fault:** (N/A)

**Remarks:**

New equipment added on handheld device

**Equipment:** DAIKIN FXSQ80P7VEB - DUCTED UNIT

**Serial No:** 5430275

**Location:** room 3

**Problems / Common Fault:** (N/A)

**Remarks:**

New equipment added on handheld device

**Equipment:** DAIKIN FXSQ80P7VEB - DUCTED UNIT

**Serial No:** 5430267

**Location:** room 4

**Problems / Common Fault:** (N/A)

**Remarks:**

New equipment added on handheld device